Stage	Source	Mag	gnitude	Probable Error	
Field work					
	Collection				
	Compaction	n effects <sup>1</sup> 0.8	gal	" 0.38%	
Lab analysis					
	Water leve	l change			
		isplacement	1 mm	" 0.12%	
Cumulative effect			_	" 0.5%	

Table 4 - Potential sources of error introduced when calculating percent (volume) coarse gravel and cobble content in sediment samples associated with Phipps Ocean Park Beach restoration project. Greatest potential source of error is associated with disturbance of *in situ* sediment compaction values. Resolution in reading immersion container calibration marks is also a potential source of error.

<sup>&</sup>lt;sup>1</sup> Field estimates suggest <u>+</u>20% of sample volume are not uncommon